

Corrigendum List of 2023 Catalogue

Page	Description	Error	Correct
18, 85	(2) Soldering	(b) ...of lead wires and	(b) ...of leader wires and
85	(2) Soldering	(c).... should NOLY be should ONLY be....
128	VUP Series Rated Voltage	10 ~ 35V	10 ~ 100V
128	VUP Series Lead spacing and diameter	Without $\phi D \geq 12.5$ mm	6.3 ~ 18 ϕ
129	VGN Series Dimension and permissible ripple current	Without 12.5 ~ 18 ϕ	6.3 ~ 18 ϕ (10 ~ 100V / 10 ~ 3,300 μ F)
137	VGN Series Lead spacing and diameter	Without 8 ~ 10 ϕ	8 ~ 18 ϕ
138	VGN Series Dimension and permissible ripple current	Without 8 ~ 10 ϕ	8 ~ 18 ϕ